

Edgar Filing: BRITISH ENERGY PLC - Form 6-K

BRITISH ENERGY PLC  
Form 6-K  
August 07, 2003

FORM 6-K

SECURITIES AND EXCHANGE COMMISSION  
Washington, D.C. 20549

Report of Foreign Issuer

Pursuant to Rule 13a-16 or 15d-16 of  
the Securities Exchange Act of 1934

August 7, 2003

BRITISH ENERGY PLC  
(Registrant's name)

3 Redwood Crescent  
Peel Park  
East Kilbride G74 5PR  
Scotland  
(Address of principal executive offices)

Indicate by check mark whether the registrant files or will file annual reports under cover Form 20-F or Form 40-F.

Form 20-F..X.. Form 40-F.....

Indicate by check mark whether the registrant by furnishing the information contained in this Form is also thereby furnishing the information to the Commission pursuant to Rule 12g3-2(b) under the Securities Exchange Act of 1934.

Yes ..... No ..X..

If "Yes" is marked, indicate below the file number assigned to the registrant in connection with Rule 12g3-2(b):

Exhibit Index

The following document (bearing the exhibit number listed below) is furnished herewith and is made a part of this Report pursuant to the General Instructions for Form 6-K:

Exhibit	Description
No. 1	RNS Announcement, re: Output Statement dated 7 August, 2003

BRITISH ENERGY plc - OUTPUT STATEMENT

A summary of net output from all of British Energy's power stations in July is given in the table below, together with comparative data for the previous

## Edgar Filing: BRITISH ENERGY PLC - Form 6-K

financial year:

	2002/03				2003/04			
	July		Year to Date		July		Year to Date	
	Output (TWh)	Load Factor (%)	Output (TWh)	Load Factor (%)	Output (TWh)	Load Factor (%)	Output (TWh)	Load Factor (%)
UK - Nuclear	5.26	74	20.66	74	5.14	72	22.18	79
UK - Coal	0.17	12	1.04	18	0.40	28	1.49	26
USA - AmerGen (50% owned)	1.77	96	6.10	84	1.84	100	7.10	98

### OVERVIEW

The output figures for both the UK and AmerGen nuclear plant remain in line with plan.

#### UK - Nuclear

##### Planned Outages

- A statutory outage was completed at Hunterston B and another started at Torness.
- Low load refuelling was carried out on both reactors Hinkley Point B and on one reactor at Heysham 2 and Torness.

##### Unplanned Outages

- Repair outages were completed on both units at Hartlepool and on one unit at Dungeness B.

### CONTACTS

John MacNamara	01355 262 574	(Media Enquiries)
Paul Heward	01355 262 201	(Investor Relations)

Find this News Release on our web-site: [www.british-energy.com](http://www.british-energy.com)

END

### SIGNATURES

Pursuant to the requirements of the Securities Exchange Act of 1934, the registrant has duly caused this report to be signed on its behalf by the undersigned, thereunto duly authorized.

Edgar Filing: BRITISH ENERGY PLC - Form 6-K

Date: August 7, 2003

BRITISH ENERGY PLC

By: \_\_\_\_\_Paul Heward\_\_\_\_\_

Name: Paul Heward

Title: Director - Investor Relations